

State of West Virginia
Office of Oil and Gas

INSPECTORS REPORT

Operator: Mt V oil & Gas


API Number: 47-87-02003

Findings:

Line from tanks to UIC well developed a leak around an existing band clamp. Ground has been remediated with lime & fertilizer, seeded and mulched.

All piping on the well head is to be replaced, and a filter container is to have a bucket put under it for when they replace it, or it may be removed completely.

Pipe line will be replaced by the end of the year or 10,200 feet at it.


Oil & Gas Inspector

8-28-2015

Date

Received
Office of Oil & Gas
SEP 1 2015

23 6 12 N 111

2305-73-77

And a hypothesis that the first part of the
road and beyond, and the road is not
the same, and the road is not the same

And the

And the road is not the same, and the road is not the same
the road is not the same, and the road is not the same
the road is not the same, and the road is not the same

And the road is not the same

And the road is not the same, and the road is not the same
the road is not the same, and the road is not the same
the road is not the same, and the road is not the same

And the road is not the same

And the road is not the same

And the road is not the same

And the road is not the same

And the road is not the same