

Project Wells Inspections Report

API	Inspection Date	Inspection Type	Comments
039-00798			
	6/2/2014	Compliance Review	Gravity fed-No flow or pressure on annulus
	6/9/2011	Compliance Review	Gravity fed-No flow or pressure on annulus
	12/15/2009	MIT Witnessed	
	1/28/2009	Routine/Periodic	In-active/shut-in / No flow or pressure on annulus
	9/13/2004	Compliance Review	well on vacumm and no pressure on well
	4/6/2001	Compliance Review	Well on vacuum and not operating. No pressure or flow on annulus.
	2/1/2000	Routine/Periodic	well is onvac fluid is being injected too slow to register
	3/10/1999	Compliance Review	WELL ON VACUUM AND NOTHING GOING IN WELL AT TIME OF INSPECTION.
	12/10/1997	Compliance Review	INJ. PRESSURE ZERO; INJ. RATE .5 BBL/HR
	2/20/1997	Compliance Review	WELL ON VACUUM AND NOT INJECTING AT TIME OF INSPECTION
	11/14/1995	Compliance Review	INJ. RATE 1/4 BBL/HR; WELL IS ON VACUUM
	2/1/1995	Compliance Review	WELL ON VACUUM - NOTHING BEING INJECTED AT TIME OF INSPECTION
	2/17/1994	Compliance Review	3 1/2 & 10" CASINGS ON VACUUM-NOTHING WAS BEING DISPOSED AT TIME OF TEST
	6/28/1993	Compliance Review	WELL ON VACUUM - BARRELL COUNTER SHOWED 1/2 TO 1 BBL. PER HR.
073-02523			
	1/25/2012	Compliance Review	New tubing installed / Inj. pressure 2,200psi / Annulus no flow or pressure / Water monitoring well repaired
	1/3/2012	Compliance Review	MIT passed
085-05076			
	9/15/2004	Compliance Review	inactive no activities no problems evident
	1/16/2001	MIT Witnessed	tested to 520psi well status changed
085-05151			
	10/17/2012	Compliance Review	Inj. at 800 psi
	11/9/2011	Compliance Review	Inj at 850psi / need security improved
	12/10/2010	Compliance Review	Pipeline pressure tested on 11/22/2010 -passing
085-07652			
	11/9/2011	Compliance Review	No flow or pressure on annulus / secondary containment repaired
	10/15/2009	Routine/Periodic	1225 psi on well / Valve closed on annulus - operator to open
	9/14/2005	Routine/Periodic	Well not in operation at time of inspection zero / zero no environmental problems
	9/12/2004	Compliance Review	no gauge on well no leaks
	9/16/2003	Violation	No gauge on well
	5/10/2002	MIT Witnessed	MIT passed Larry Parrish on location
	5/19/1999	Compliance Review	WELL NO OP. AT TIME OF INSP.;SOME SPILLAGE AT WELL; TANK DIKE FULL

API	Inspection Date	Inspection Type	Comments
	8/7/1998	Compliance Review	GRAVITY FEED FROM 210 BBL TANK
	9/3/1997	Compliance Review	WELL IS GRAVITY FEED FROM A 210 BBL TANK LOCATED ON SITE.
	8/13/1996	Compliance Review	NOT INJ. AT TIME OF VISIT; WELL PROB. LOADED UP AND WON'T TAKE FLUID.
	3/20/1996	MIT Witnessed	M.LEWIS-PRESSURE TEST TUBING BY 4 1/2 ANNULUS- PASSED MIT.
	12/13/1995	Routine/Periodic	SAM HERSMAN AND MIKE LEWIS MADE INSPECTION
085-08350			
	4/7/2010	MIT Witnessed	
	9/14/2005	Routine/Periodic	well not in operation at time of inspection zero/zero very clean well site
	5/21/2002	Compliance Review	Adding Compliance Revies to count as inspection
	5/21/2002	MIT Witnessed	Passed MIT Larry on location
	5/19/1999	Compliance Review	GRAVITY FED; ZERO PSI ON TUBING & CASING; SOME SPILLAGE ON LOCATION
	8/7/1998	Compliance Review	ROAD BLOCKED BY TREES; WILL CONTACT OPERATOR TO HAVE REMOVED; FOLLOW-UP
	8/18/1997	Compliance Review	GRAVITY FLOW; INJ. RATE 114 BBL/WK; NO FLOW OR PRESSURE ON ANNULUS
	1/30/1996	MIT Witnessed	FLUID LEVEL SHOT ON TUBING ANNULUS BEFORE AND AFTER INJECTION. PASSED.
	1/5/1996	Compliance Review	ZERO PRESS. ON ANNULUS AND TUBING. INJ. RATE APPROX. 1 TO 2 BBL. HR.
	12/13/1995	Routine/Periodic	SAM HERSMAN AND MIKE LEWIS MADE INSPECTION
087-00658			
	1/14/2009	Compliance Review	well abandoned - needs plugged - submit letter to Applied
	9/27/2004	Compliance Review	well abandoned
	8/28/2002	Routine/Periodic	Still out of service needs to be plugged
	4/6/2001	Compliance Review	Out of service-Needs to be pugged
	2/15/2000	Compliance Review	temporally out of service o psi on 2 3/8" no flow no preasure
	3/10/1999	Compliance Review	ZERO PSI ON 2 3/8"; NO FLOW OR PRESSURE ON ANNULUS
	8/12/1998	Compliance Review	ZERO PSI ON 2 3/8"; NO FLOW OR PRESSURE ON ANNULYS
	8/12/1997	Compliance Review	WELL NOT INJECTING AT TIME OF INSPECTION; TOOK GPS READING
	6/25/1996	Compliance Review	WELL NOT PRODUCING; PUMPER SAYS IT IS USED ONLY SPARINGLY
	9/8/1995	Compliance Review	NO PRESSURE ON 2 3/8" OR ON ANNULUS; PERMIT EXPIRED
	5/4/1994	Compliance Review	WELL IS SHUT DOWN. PERMIT EXPIRED.
	9/24/1993	Compliance Review	ZERO PRESS. ON 2 3/8"; NO FLOW OR PRESS. ON ANN; PUMP NOT RUNNING TODAY
	9/18/1992	Compliance Review	RE-CHECKED ANNULUS PRESSURE
	9/10/1992	Compliance Review	NO FLOW OR PRESSURE ON ANNULUS
	8/13/1992	Compliance Review	450 PSI ON TUBING;WELL NOT OPER. AT VISIT; NO FLOW OR PRESS. ON ANNULUS

API	Inspection Date	Inspection Type	Comments
087-01056			
	4/9/2014	Compliance Review	MIT passed / No flow or pressure annulus
	10/12/2008	Compliance Review	0 pressure 0 flow
	9/27/2004	Compliance Review	0 pressure 0 flow no pumping has been shut in for four years ? permit renewal in office
	1/14/2000	Compliance Review	out of service tubing on vac future status wili be known after Jan 01 company has been sold
	3/12/1999	Compliance Review	2 3/8" ON VACUUM AT TIME OF INSP.; NO FLOW OR PRESSURE ON ANNULUS
	8/10/1998	Compliance Review	INJ. PRESS. 2 3/8" ON VAC.; NO FLOW OR PRESS. ON ANN.;FIELD TEMP. DOWN
	8/12/1997	Compliance Review	WELL NOT OPERATING AT TIME OF INSP.; GAUGE ON TUBING NEEDS REPLACED
	7/24/1996	Compliance Review	INJ. PR. 680 PSI; NO FLOW/PR. ON ANN.;PUMP NEEDS WORK/SHOOTING S. WATER
	1/24/1995	Compliance Review	525 PSI ON INJ. TUBING; INJ. RATE 15 BBL/DAY; NO FLOW/PRESS. ON ANNULUS
	4/21/1994	Compliance Review	INJ. PRESS. 540 PSI; INJ. RATE 87 BBL/DAY;NO FLOW OR PRESS/ALL VLVS OPEN
	1/31/1994	Other	(FROM HOMER'S WEEKLY)
	9/22/1993	Compliance Review	INJ. PRESS. 245 PSI ON GAUGE; 30 BBL/HR; NO FLOW OR PRESS. ON ANN.
	9/10/1992	Compliance Review	NOT INJECTING AT TIME OF INSPECTION. ZERO PSI ON TUBING AND ANNULUS.
	1/6/1992	MIT Witnessed	H. DOUGHERTY-PRESSURE TEST 4 1/2 TO 1300 PSI/10 PSI BLED OFF/PASSED
087-01572			
	11/9/2011	Compliance Review	Well is producing from 2 3/8 and 5" / no fluid on annulus
	5/6/2009	Compliance Review	Gravity fed / Injecting down 4 1/2 and producing through tubing
	9/4/2007	Compliance	gravity
	4/6/2001	Compliance Review	Gravity flow of 1 Bbl/day.
	8/28/2000	Compliance Review	dual-purpose well annulus used to gravity flow salt water production through tow and seve eights no preasure on injection side
	6/22/1999	Compliance Review	ZERO INJ. PRESS.; WELL NOT INJECTING AT TIME OF INSPECTION
	4/21/1998	Compliance Review	WELL GRAVITY FEEDS AT 1 BBL OF BRINE PER DAY
	8/12/1997	Compliance Review	WELL FENCED IN AND LOOKS GOOD; ACTIVELY PRODUCING UP TUBING; TOOK GPS RD
	6/25/1996	Compliance Review	PUMP JACK ON WELL - WELL PRODUCING - INJ. LINE PLUMBED INTO ANNULUS
	12/14/1995	MIT Witnessed	ANNULUS PRESSURE CHECKED BEFORE, DURING AND AFTER INJECTION. NO CHANGE.
	6/27/1995	Compliance Review	NO FLOW/PRESS ON INJ. ZONE. NEW 2" VALVE ON HEAD TO SHOOT FL. LVL THROUG
	6/24/1994	Compliance Review	GRAVITY FED; NO FLOW OR PRESS. ON ANNULUS, 2" PIPE OFF OF HEAD.

API	Inspection Date	Inspection Type	Comments
	2/3/1993	Compliance Review	OPERATOR TO UNHOOK LINE FROM PUMP TO INJECTION LINE.
	2/20/1992	Compliance Review	METER NOT HOOKED UP;WATER FLOWING THROUGH PUMP;PUMP LEAKING;REPAIR BYPAS
087-01578			
	11/9/2011	Compliance Review	No cement on surface casing / well is producing from 2 3/8
	5/6/2009	Compliance Review	Gravity fed / injecting down 4 1/2 and producing through tubing
	9/4/2007	Compliance Review	gravity
	4/6/2001	Compliance Review	Gravity flow 1 Bbl/day
	1/26/2000	Compliance Review	zero psi gravity flow system active well
	6/22/1999	Compliance Review	ZERO INJ. PRESSURE; ANNULUS OPEN - NO FLOW
	4/21/1998	Compliance Review	WELL GRAVITY FEEDS AT ONE BBL PER DAY
	4/21/1998	MIT Witnessed	MLEWIS-GSMITH FLUID DEPTH ON ANNULUS WAS 150 FEET.
	8/12/1997	Compliance Review	ACTIVELY PROD. UP TUBING; NEED TO CHECK TRANSFER; TOOK GPS READING
	6/25/1996	Compliance Review	PUMP JACK ON WELL - INJ. LINE PLUMBED UP TO 8" ANNULUS
	6/27/1995	Compliance Review	FLUID GOING ON GRAVITY BETWEEN 8 5/8" & 4 1/2"
	2/9/1994	Other	SHOW CAUSE HEARING AT NITRO OFFICE
	10/6/1993	Compliance Review	(FROM HOMER'S WEEKLY)
	2/3/1993	Compliance Review	TANK NEEDS TO BE TAKEN OUT AND LINE SPLICED.
	2/20/1992	Compliance Review	NO INJ. PRESSURE; NO METER ON WELL; NO FLOR OR PRESSURE ON ANNULUS
087-01591			
	10/30/2008	Compliance Review	0 Flow 0 Pressure / pump has not motor / Diked area with some contamination
	4/6/2001	Compliance Review	Zero psi on tubing-Well does not appear to have operated for a while.
	1/26/2000	Compliance Review	active well zero psi on tubing no flow or pressure at time of inspection
	3/16/1999	Compliance Review	ZERO PSI ON 2 3/8" NO FLOW OR PRESSURE ON ANNULUS
	8/12/1998	Compliance Review	ZERO PSI - WELL NOT OPERATING AT TIME OF INSPECTION
	4/15/1998	Compliance Review	WELL HAS NOT BEEN USED RECENTLY
	7/3/1997	Compliance Review	NOT OPERATING AT TIME OF INSPECTION; TOOK GPS READING
	6/25/1996	Compliance Review	WELL NOT OPERATING AT TIME OF VISIT; NO LEAKS; TANKS DIKED; LOOKS GOOD
	6/27/1995	Compliance Review	INJ PRES 1050 PSI; NO FLOW OR PRESSURE ON ANNULUS
	6/24/1994	Compliance Review	0 PSI ON 2 3/8" TUBING; NO FLOW OR PRESS. ON ANN. NO SALT WATER IN TANK
	9/16/1993	Compliance Review	INJ. PRESS 250 PSI ON 2" TUBING; NO FLOW OR PRESS. ON 2 3/8" x 4 1/2"
	8/13/1992	Compliance Review	NOT OPERATING AT TIME OF INSPECTION; NO FLOW OR PRESSURE ON ANNULUS
	1/15/1992	MIT Witnessed	G. SMITH-P. TEST 4 1/2 ANN. TO 1977 PSI/20 MIN.-77 PSI BLED OFF-PASSED.
087-01623			

API	Inspection Date	Inspection Type	Comments
	8/3/2000	Compliance Review	active well no flow no pressure at time of inspection
	6/22/1999	Compliance Review	ZERO INJ. PRESS.; NOT INJ. AT TIME OF INSP.; NEED NEW VLV FOR ANN. PRESS
	8/19/1998	Compliance Review	
	4/15/1998	Compliance Review	PUMP NOT RUNNING AND NO CHART; WILL DO AGAIN NEXT MONTH OR SO.
	8/12/1997	Compliance Review	HAD LEAK; REPAIRED; NEED TO PR. TEST LINE BEFORE INJECTING; FOLLOW-UP
	7/25/1997	Other	COMPLAINT 97-92
	7/23/1997	Other	COMPLAINT 97-92
	6/2/1997	Violation	VIOLATION #8793 ABATED
	5/13/1997	Violation	FROM HOMER'S WEEKLY
	7/11/1996	Compliance Review	NOT OPERATING AT TIME OF INSPECTION; ZERO PSI ON TUBING
	9/25/1995	Compliance Review	INJ. PRESS. 615 PSI; INJ. RATE 20 BBL/HR. NO FLOW/PRESS. ON ANNULUS
	9/20/1994	Compliance Review	INJ. PRESS. 530 PSI ON REC. WELL PUMPED 1 TIME IN 9 DAYS; NO FLOW ON ANN
	9/24/1993	Compliance Review	2 3/8" TUBING ON VAC. AT WELL HEAD; 60 PSI ON RECORDER
	8/13/1992	Compliance Review	ZERO PSI ON TUBING;WELL NOT OPER. AT VISIT;NO FLOW OR PRESS. ON ANNULUS

087-01926

	8/28/2002	Compliance Review	Gauge connection still bad 200 PSI estimated well in operation
	3/8/2000	Compliance Review	dual completed well pressure on 2 3/8" no way to gauge injection line is disconnected from injection tubing
	6/17/1999	Compliance Review	INJECTION LINE UNHOOKED; NO MOTOR ON PUMP JACK
	2/10/1999	Compliance Review	WELL IS TEMPORARILY SHUT-DOWN
	8/12/1998	Compliance Review	2" INJ. LINE VALVE LEAKING AND NEEDS REPLACED.
	8/12/1997	Compliance Review	NOT INJ.; NO PRESS. ON TUBING; MOTOR TAKEN OFF PUMP JACK
	6/25/1996	Compliance Review	INJ. PRESS. ZERO; NO FLOW OR PRESS. ON ANNULUS; DUAL COMPLETION WELL
	9/22/1995	Compliance Review	NOT IN USE AT THIS TIME; NEW OWNER PLANS TO PUT BACK INTO SERVICE.
	6/21/1994	MIT Witnessed	G. SMITH FLUID LEVEL AT 1530 FT. BEFORE AND AFTER INJECTION OF 1 HOUR.
	6/14/1994	Compliance Review	NOT OPERATING AT TIME OF INSPECTION
	9/29/1993	Compliance Review	ZERO PSI ON 2 3/8" INJ. NO FLOW OR PRESSURE ON ANNULUS
	9/10/1992	Compliance Review	DUAL COMP. WELL-NOT INJECTING AT TIME OF INSPECTION-5 PSI ON TUBING.

103-01415

	12/2/2009	MIT Witnessed	Well passed MIT at 1080PSI. Annulus to be monitored-gauge
	2/17/1999	Other	WELL NOT OP.;HAS BEEN GR. FEED 2 BBL/DAY; PRESS. UP QUICKLY;NOT MUCH H2O
	8/24/1998	Compliance Review	INJ. ON VACUUM; NO PRESSURE ON 4 1/2" ANNULUS
	1/8/1998	MIT Witnessed	M.LEWIS- PRESSURE TEST TUBING. PASSED TEST.

API	Inspection Date	Inspection Type	Comments
	8/26/1997	Compliance Review	NOT INJECTING AT TIME OF INSPECTION; NEEDS ACID FLUSH
	4/2/1997	Routine/Periodic	WELL NOT OPERATING YET; NEED TO SET UP PUMP; TANKS DIKED & IN PLACE
	8/12/1996	Compliance Review	WELL HAS NOT BEEN COMPLETED YET; SHOULD BE COMPLETED BY 11/15/96
107-00819			
	8/11/2011	Compliance Review	Well did not pass MIT - needs repaired
	9/15/2004	Compliance Review	well out of operation permit expired operator say will repermit
	12/8/1999	Routine/Periodic	this well was abandoned at the inspection
	8/11/1997	Compliance Review	NOT CONVERTED; VIOLATION & FAILURE TO ABATE HAS BEEN ISSUED FOR GAS LEAK
	6/9/1997	Routine/Periodic	HOMER'S WEEKLY
	9/30/1996	Compliance Review	PERMIT ISSUED - NOTHING DONE ON WELL AS YET.
109-01433			
	12/17/2013	Compliance Review	No leaks observed
	2/20/2013	Compliance Review	MIT passed - pressure annulus to 730psi for 28 minutes
	3/3/2009	Routine/Periodic	Well currently injecting / Settling ponds associated with well