


8/12/06

**Nabor's Rig #44; Crosby 25-3
Well, Windsor Oil & Gas**



Small blow-holes on county road releasing drilling mud & condensate.

8/12/06

**Condensate flowing down
county road going to
emergency pit.**



8/12/06

**Small blow-hole on county
road.**



8/12/06

**Small blow-hole on county
road.**




8/12/06

**Small blow-hole on county
road.**




8/12/06

**Condensate percolating from
small blow-hole.**



8/12/06

**Small blow-hole on county
road.**



8/12/06

Multiple blow-holes on road.




8/12/06

**Small crack on cut releasing
drilling mud & condensate.**



8/12/06

**Small crack on cut releasing
drilling mud & condensate.**



8/12/06

**Condensate & drilling mud
flowing off cut bank,
collecting behind drilling
shacks.**



8/12/06

**Condensate percolation on
location.**



8/12/06

**Blooie line overspray of
drilling fluids & condensate.**



















