

COMPLETE WELL INSPECTION FORM

ASSIGNED API NUMBER 47-_____

GPS DATE 6/26/2014

API NUMBER 47- 109-01433

WELL OPERATOR EnerVest

FARM NAME Loup Creek

WELL NUMBER LC-19 SWD (UIC)

A. THE ACCESS ROAD MEETS ALL REQUIREMENTS? (22-6-30, 35CSR-4-16)

- | | | | | |
|----|------------------------------------|---|-----------------------------|------------------------------|
| 1. | CULVERTS PROPERLY SIZED AND SPACED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 2. | DISSIPATING DEVICES | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 3. | PROPERLY MAINTAINED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 4. | DIVERSION DITCHES IN PLACE | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |

B. THE WELL AND LOCATION ARE PROPERLY EQUIPPED AND RECLAIMED? (22-6-30, 22-6-6, 35CSR-4-16)

- | | | | | |
|----|---|---|-----------------------------|------------------------------|
| 1. | API NUMBER | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 2. | DIVERSION DITCHES | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 3. | ALL DISTURBED AREAS RECLAIMED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 4. | IS SITE FREE OF OIL, GAS AND SALT WATER LEAKS | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 5. | IS WELL PRODUCING | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 6. | PRODUCTION REPORTS BEEN FILED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |

C. DOES THE SPILL PREVENTION MEET ALL REQUIREMENTS?(22-6-7, 35CSR1-7, 35CSR-4-11 TO 17)

- | | | | | |
|----|--|---|-----------------------------|------------------------------|
| 1. | ARE TANKS PROPERLY EQUIPPED WITH THE FOLLOWING: | | | |
| | A. SECONDARY CONTAINMENT | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | C. EQUALIZING LINES | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | B. VALVES | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| 2. | ARE SECONDARY CONTAINMENT STRUCTURES PROPERLY CONSTRUCTED: | | | |
| | A. IMPERVIOUS | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | B. DIKES PROPERLY SIZED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | C. SURFACE WATER PROPERLY DRAINED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | D. VALVES INSTALLED ON DIKE DRAINS | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| | E. DIKE DRAIN VALVES CLOSED | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |

D. IS SALT WATER BEING PROPERLY DISPOSED OF? (22-6-7) ☒ YES ☐ NO ☐ N/AE. WAS THIS INSPECTION ROUTINE? ☒ YES ☐ NO
SPECIFY (COMPLAINT, RANDOM, ETC.) _____F. IS THIS WELL PART OF A SECONDARY RECOVERY FIELD? YES ☒ NOG. WERE ENFORCEMENT ACTIONS TAKEN AS A RESULT OF THIS INSPECTION? YES ☒ NO
SPECIFY (VIOLATION, WARNING LETTER) _____

COMMENTS: Loading Bay Lat 37.7884421 Long 81.5021113

Tank Battery Lat 37.7876829 Long 81.5025872

Well Head Lat 37.7774090 Long 81.5109810

Well head in the hollow. Access road down the mountain rough and rocky.

Well tender was at the unloading battery he said a bear has been tearing up equipment around tank battery.

Received
Office of Oil & Gas

JUL 02 2014

DATE 6/26/2014

INSPECTOR Ross Eller